

APPENDIX G

Appendix G contains photographs in Plate Nos. 1 to 27 where Plate Nos. 1 to 24 show crack pattern on tension face for specimen nos. 1 to 24, Plate No. 25 shows load testing machine, Plate No. 26 is of specimen MUP 2 4/5 after failure on testing machine and Plate No. 27 shows crushing of concrete on compression face of specimen nos. 13 and 14.







Plate Nos. 1 to 4
Crack Pattern ;
Specimen Nos. 1 to 4







Plate Nos. 5 to 8
Crack Pattern ;
Specimen Nos. 5 to 8







Plate Nos. 9 to 12
Crack Pattern ;
Specimen Nos. 9 to 12







Plate Nos. 13 to 16
Crack Pattern ;
Specimen Nos. 13 to 16






Plate Nos. 21 to 24
Crack Pattern ;
Specimen Nos. 21 to 24




Plate No. 25
 Load Testing Machine : 200 T. Capacity :
 Hinge Device is seen on cradle




Plate No. 26
 Specimen MUP "2" 4/5 , on Testing Machine
 Specimen is seen mounted on hinge device




Plate No. 27
 Cracks on compression face and
 spalling of concrete : Specimens 13 and